

| Speed | 0.5 bar (7 psi) | 0.8 bar (11 psi) | 1.0 bar (14 psi) | 1.2 bar (17 psi) | 1.4 bar (20 psi) | 1.6 bar (23 psi) | 1.8 bar (26 psi) | 2.0 bar (28 psi) | 2.2 bar (31 psi) | 2.4 bar (34 psi) | 2.6 bar (37 psi) | 2.8 bar (40 psi) | 3.0 bar (43 psi) | 3.2 bar (46 psi) | 3.4 bar (48 psi) | 3.5 bar (50 psi) |
|--------------|------------------------------------|-------------------------------------|-------------------------------------|-------------------------------------|-------------------------------------|-------------------------------------|-------------------------------------|-------------------------------------|-------------------------------------|-------------------------------------|-------------------------------------|-------------------------------------|-------------------------------------|-------------------------------------|-------------------------------------|-------------------------------------|
| 50 FR | 2510 | 3195 | 3675 | 4165 | 4605 | 5040 | 5450 | 5850 | 6300 | 6750 | | | | | | |
| 50 DrW | 1770 | 2250 | 2585 | 2925 | 3260 | 3600 | 3885 | 4160 | 4465 | 4770 | | | | | | |
| 40 FR | 2790 | 3550 | 4085 | 4625 | 5115 | 5600 | 6055 | 6500 | 7000 | 7500 | | | | | | |
| 40 DrW | 1965 | 2500 | 2875 | 3250 | 3625 | 4000 | 4315 | 4625 | 4965 | 5300 | | | | | | |
| 25 DrW | 2335 | 2975 | 3420 | 3865 | 4310 | 4760 | 5135 | 5505 | 5905 | 6305 | | | | | | |
| 10C | 3375 | 4115 | 4605 | 5100 | 5620 | 6135 | 6650 | 7170 | 7685 | 8155 | 8610 | 9055 | 9480 | 9950 | 10425 | 10650 |
| 10 FR | 3675 | 4600 | 5235 | 5890 | 6535 | 7130 | 7715 | 8300 | 8835 | 9405 | 10015 | 10620 | | | | |
| 10 DrW | 2585 | 3240 | 3685 | 4130 | 4595 | 5050 | 5510 | 5920 | 6295 | 6680 | 7090 | 7505 | | | | |